

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN **PLICATE***
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

029847

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER Convert to Water Injection	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Shenandoah Oil Corporation	8. FARM OR LEASE NAME Shugart "D"
3. ADDRESS OF OPERATOR 1018 Commerce Bldg., Ft. Worth, Texas 76102	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' FNL & 2310' FEL Sec. 30-18S-31E, Eddy County, N.M.	10. FIELD AND POOL, OR WILDCAT Shugart (Y. SR. Q, G)
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30-18S-31E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) Unknown
	12. COUNTY OR PARISH Eddy
	13. STATE N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☒	CHANGE PLANS	☐
(Other) Convert to Water Input			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 3829' - PBD 3808'. It is planned to convert to water injection as follows:

1. Pull rods and tubing.
2. Run sand pump & C.O. to TD.
3. Run perforation log to check perforations 3762-13778 (96 holes) and make perforation in 5-1/2' csg. opposite Penrose section 2385-2404 and 2452-2454'.
4. Run internally plastic coated tubing with necessary packers to isolate each zone and to be controlled with downhole flow regulators.

Note: This work being performed in accordance with the N. Mexico OCC Order #R-3481 (Case #3779)

RECEIVED

SEP 10 1963

SEP 10 1963

18. I hereby certify that the foregoing is true and correct

SIGNED

T. J. Bates

TITLE **Supvr., Secondary Recovery**

DATE **Sept. 17, 1963**

(This space for Federal or State office use)

TITLE

DATE

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

SEP 10 1963

R. L. BELMANN

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.