

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other Instructions on reverse side)

Budget Bureau No. 1004-0115
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-02460

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Culwin Queen Unit

8. FARM OR LEASE NAME

9. WELL NO.

#7

10. FIELD AND POOL, OR WILDCAT

Shugart Y/Qn/7R

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 31, T18S, R31E; NMPM

12. COUNTY OR PARISH 13. STATE

Eddy

NM

RECEIVED
SUMMARY NOTICES AND REPORTS ON WELLS

1. This form is to be filled out to reopen or plug back to a different reservoir.
2. Submit in triplicate (one copy for each reservoir) for such proposals.

APR 28 '89

C. C. D.
ARTESIA OFFICE

1. WELL TYPE
GULF WELL ☐ GAS WELL ☐ OTHER ☒

2. NAME OF OPERATOR

John H. Trigg

3. ADDRESS OF OPERATOR

P.O. Box 520 ; Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 592'³⁵ FWL ; SWSW

14. PERMIT NO.

15. ELEVATIONS (Show whether ☒ RT, GR, etc.)

3526'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

(Temp) RANDOM*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Propose to perform csg. integrity test as per B.L.M. instructions.

Last csg. test was 7/31/86. Since that time, 4 1/2" retainer was set @ 2860' and 50 sx CI'C'w/ 2% CaCl was squeezed below it to isolate perfs @ 2919' - 2952'. A 35' cmt. cap was placed on top of the retainer. (work done 1/26/89 by Halliburton).

RECEIVED
APR 26 11 23 AM '89

18. I hereby certify that the foregoing is true and correct

SIGNED

Lee Robinson

TITLE

Supervisor, Pumper

DATE

4-26-89

(This space for Federal or State office use)

APPROVED BY

Shammy Shaw

For:

CHIEF, MINERAL RESOURCES

DATE

4-27-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side