ENERGY AND MINERALS DEPARTMENT	
es, or contractives	
DISTRIBUTION INCLUIVED NO. BOX 2088	Form C-103
SANTA FE, NEW MEXICO 87501	Revised 10-1-7
U.S.C.S. APR -8 1967	5a. Indicate Type of Lease
AND OFFICE	State X
O. C. D. ARRESIA, OFFICE	5, State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	B-2023 ·
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DECPEN OR PLUC SACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PHOPOSALS.)	
OIL WELL OTHER-	7. Unit Agreement Name
ENERGY RESOURCES OIL & GAS CORPORATION	8. Farm or Lease Name STATE
. Address of Operator 4849 GREENVILLE AVE., SUITE 730, DALLAS, TX 75206	9. Well No. 1-32
Location of Well	
UNIT LETTER B 330 PEET PROM THE NORTH 2310	10. Field and Pool, or Wildcar
THE EAST LINE, SECTION 32 TOWNSHIP SANGE NAMES	
TOWNSHIP RANGE HMPM	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County EDDY
6. Charle Appropriate Part To I I'm N	
Check Appropriate Box To Indicate Nature of Notice, Report or Or NOTICE OF INTENTION TO: SUBSEQUEN	ther Data T REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.	g estimated date of starting any proposed
PLUGGING PROCEDURE	
1. Set C.I.B.P. @ 2500' - Dump 35' cmt in 5 1/2" csg. on to	n of CTPR
2. Load hole with 9.5# mud.	p or c.1.1. B.
3. Cut 5 1/2" csg @ 1925' - Set 100' plug over 5 1/2" csg st	ub.
4. Pull casing up to base 8 5/8" csg @ 905' -Set 100' cmt pl	
5. Pull casing and set 10' cmt plug @ surface.	
6. Set regulation well identification marker in top of surfa	ce casing.
to a nd an analysis of the second se	
. I hereby cortify that the information above is true and complete to the best of my knowledge and belief.	· · · · · · · · · · · · · · · · · · ·
	•
PRODUCTION MANAGER	4-4-85

OIL AND GAS INSPECTOR

APR 1 0 1985