

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATION
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL NO

NM-10190

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

East Shugart Unit

8. FARM OR LEASE NAME

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Shugart Yates, 7R, Qn, Grbg

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec.35-T18S-R31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Hondo Oil & Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 2208, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

308' FNL & 990' FWL

80' (505)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3648' GR

18.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

4/5/89 Perforated 4192-4246' with 8 holes.

4/6/89 Acidized 4192-4246' with 500 gal. 15% NEFE acid.

4/7/89 Reacidized 4192-96' (5 holes) with 500 gal. 15% NEFE acid.
Swabbed back load - got black sulphur water.

4/8/89 Set CIBP @ 4145'. Perforated 4020-58' with 10 holes.
Acidized 4020-58' with 1000 gal. 15% NEFE acid. Swabbed
back load - got black sulphur water.

4/9/89 Set squeeze retainer @ 4000'. Squeezed 4020-58' with
125 sx. Class "C" cement. Pressured to 3200 psi - held
okay.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Petroleum Engineer

DATE 4/13/89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD
DATE

APR 24 1989

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO