~ 5	•••••	CL _* COMMISSION
orm 3160-SRECEIVED UNI	ITED STATES Drawer I	
SEP 26 10 52 M SUNDRY NOTICES	NT OF THE INTERIOR Artesia	Budget Bureau No. 1004-0135
IN BAREAU OF	LAND MANAGEMENT	Expires March 31, 1993 5. Lease Designation and Serial No
26 10 52 mil		NM1019
		6. If indian. Allonce or Tribe Name
Do not use this form for proposals to de CARLA IN Use "APPLICATION FO	rill or to deepen or reentry to a different PR PERMIT—" for such proposals RECENT	reservoir.
-	T IN TRIPLICATE	7. If Unit or CA. Agreement Designation 14-08-001-11572
. Type of Well Oil Gas Well Other	OCT 20.	
Name of Operator Devon Energy Corporation (Neva	ada) O. C. D	East Shugart Unit #10
Address and Telephone No.	ARIESIA, OF	9. API Well No. 30-015-05701
20 N. Broadway, Suite 100, OKC		50-015-05701
Location of Well (Footage, Sec., T., R., M., or Survey De		10. Field and Pool, or Exploratory Area Shugart (Y-SR-Q-G)
		11. County or Parish, State
2310' FNL & 2310' FEL, Sec. 3	5-T18S-R31E, Unit G	Eddy, NM
	B) TO INDICATE NATURE OF NOTIC	E, REPORT, OR OTHER DATA
	TYPE O	FACTION
Notice of Intent	Abendonment	
		Change of Plans
	Recompletion	Change of Plans
Subsequent Report	Recompletion Plugging Back	
Subsequent Report	Recompletion Plugging Back Casing Repair	New Construction
	Recompletion Plugging Back Cating Repair Altering Cating	New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection
Subsequent Report	Recompletion Plugging Back Casing Repair Ahnring Casing test casin	New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Ig and Dispose Water
Subsequent Report		New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Ig and Dispose Water
 Subsequent Report Final Abandonment Notice Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vertical 09-06-94 thru 09-07-94 Pulled rods and work string to 3320'. Ran 7" tension papacker at 3012' then 2700', 2380', 1763 press'd to 500 psi, held OK. POH w/pact 09-08-94 thru 09-12-94 Ran cup-type F testing csg while coming up hole. The fet 1705'. Interval 1705-1076' did not hold 1201' and 1201-1139' tested OK. Leaker 1 BPM. Still have another hole above 11 w/retrieving head. Washed and circ'd sc OK. Set packer at 1076'. Press'd to 500 leaked. Reset packer at 669', tested OK. 	Recomptetion Plugging Back Deter test casing Attering Casing Attering Casing Attering Casing Conter test casing Attering Casing A	New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Ieak Iwater Shut-Off Conversion to Injection Ieak Iwater Shut-Off Conversion to Injection Ieak Iwater Shut-Off Conversion to Injection Iteak Iwater Report results of matupit completions at Weil Completion of Accompletion Appen and Leg form. date of starting any proposed work. If well is directionally drill as bad. LD all tbg. Ran 6 1/4" bit on 2 7/8" g to 500 psi but did not hold press. Reset of these settings. Reset packer at 508', on Early. Tested RBP to 1000 psi, held OK. Began 12666-2954', 2954-2644', 2644-2330', 2330-10 to 500 psi, held OK. The intervals 1389-10 annulus, would not hold press test at ad fill on RBP. TOH, removed packer. TIH 07' and reset. Tested RBP to 1000 psi, held it o 500 psi, held OK. Reset packer at 638', n 650-669'. Ran packer and retrieving head. rods in singles. LD 106 jts 2 7/8" tbg (work CEP) and Factors GEP and Factors
 Subsequent Report Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vertical 09-06-94 thru 09-07-94 Pulled rods and work string to 3320'. Ran 7" tension parpacker at 3012' then 2700', 2380', 1763 press'd to 500 psi, held OK. POH w/pact 09-08-94 thru 09-12-94 Ran cup-type Ft testing csg while coming up hole. The ft 1705'. Interval 1705-1076' did not hold 1201' and 1201-1139' tested OK. Leaker 1 BPM. Still have another hole above 11 w/retrieving head. Washed and circ'd sc OK. Set packer at 1076'. Press'd to 500 leaked. Reset packer at 669', tested OK. Latched RBP. POH w/tbg, packer and R string). Packed off wellhead. SI. RD Latched RBP. 	Recomptetion Plugging Back Coming Repair Aharing Coming Anaring Coming Solate casing Tisolate cas	New Construction Non-Routuse Fracturing Water Shut-Off Conversion to Injection Ieak Iteak Outpose Water (Non: Report results of multiple completion on Recompletion and Leg torm. date of starting any proposed work. If well is directionally drill as bad. LD all tbg. Ran 6 1/4" bit on 2 7/8" g to 500 psi but did not hold press. Reset of these settings. Reset packer at 508', on Early. Tested RBP to 1000 psi, held OK. Began 2666-2954', 2954-2644', 2644-2330', 2330- to 500 psi, held OK. The intervals 1389- d annulus, would not hold press test at ad fill on RBP. TOH, removed packer. TIH 07' and reset. Tested RBP to 1000 psi, held 16 500 psi, held OK. Reset packer at 638', n 650-669'. Ran packer and retrieving head. rods in singles. LD 106 jts 2 7/8" tbg (work CEP'
 Subsequent Report Final Abandonment Notice Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vertical 09-06-94 thru 09-07-94 Pulled rods and work string to 3320'. Ran 7" tension papacker at 3012' then 2700', 2380', 1763 press'd to 500 psi, held OK. POH w/pact 09-08-94 thru 09-12-94 Ran cup-type R testing csg while coming up hole. The fet 1705'. Interval 1705-1076' did not hold 1201' and 1201-1139' tested OK. Leaket 1 BPM. Still have another hole above 11 w/retrieving head. Washed and circ'd sc OK. Set packer at 1076'. Press'd to 500 leaked. Reset packer at 669', tested OK. Latched RBP. POH w/tbg, packer and R string). Packed off wellhead. SI. RD Latched RBP. POH w/tbg, and correct. 	Recomptetion Plugging Back Cating Repair Alaring Cating Alaring Cating Solate casing So	New Construction Non-Routuse Fracturing Water Shut-Off Conversion to Injection I teak I teak Outpose Water (Non: Report results of multiple completions on Weil Completion of Recompletion Argon and Leg term. date of starting any proposed work. If well is directionally drail as bad. LD all tbg. Ran 6 1/4" bit on 2 7/8" g to 500 psi but did not hold press. Reset of these settings. Reset packer at 508', on Early. Tested RBP to 1000 psi, held OK. Began 5266-2954', 2954-2644', 2644-2330', 2330-10 500 psi, held OK. The intervals 1389-10 annulus, would not hold press test at ad fill on RBP. TOH, removed packer. TIH 07' and reset. Tested RBP to 1000 psi, held 10 500 psi, held OK. Reset packer at 638', in 650-669'. Ran packer and retrieving head. rods in singles. LD 106 jts 2 7/8" tbg (work CEP' and Factor and retrieving head. I 8 199
Subsequent Report Final Abandonment Notice Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vertical 09-06-94 thru 09-07-94 Pulled rods and work string to 3320'. Ran 7" tension par packer at 3012' then 2700', 2380', 1763 press'd to 500 psi, held OK. POH w/pact 09-08-94 thru 09-12-94 Ran cup-type F testing csg while coming up hole. The for 1705'. Interval 1705-1076' did not hold 1201' and 1201-1139' tested OK. Leaker 1 BPM. Still have another hole above 11 w/retrieving head. Washed and circ'd sc OK. Set packer at 1076'. Press'd to 500 leaked. Reset packer at 669', tested OK. Latched RBP. POH w/tbg, packer and R string). Packed off wellhead. SI. RD Latched RBP. POH w/tbg, macker and R string). Packed off wellhead. SI. RD Latched Mattheward	Recomptetion Plugging Back Cating Repair Alaring Cating Alaring Cating Solate casing So	New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Ieak Iwater Shut-Off Conversion to Injection Ieak Iwater Shut-Off Conversion to Injection Ieak Iwater Shut-Off Conversion to Injection Iteak Iwater Report results of matupit completions at Weil Completion of Accompletion Appen and Leg form. date of starting any proposed work. If well is directionally drill as bad. LD all tbg. Ran 6 1/4" bit on 2 7/8" g to 500 psi but did not hold press. Reset of these settings. Reset packer at 508', on Early. Tested RBP to 1000 psi, held OK. Began 12666-2954', 2954-2644', 2644-2330', 2330-10 to 500 psi, held OK. The intervals 1389-10 annulus, would not hold press test at ad fill on RBP. TOH, removed packer. TIH 07' and reset. Tested RBP to 1000 psi, held it o 500 psi, held OK. Reset packer at 638', n 650-669'. Ran packer and retrieving head. rods in singles. LD 106 jts 2 7/8" tbg (work CEP) and Factors GEP and Factors
 Subsequent Report Final Abandoament Notice Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and the vertical 09-06-94 thru 09-07-94 Pulled rods and work string to 3320'. Ran 7" tension parpacker at 3012' then 2700', 2380', 1763 press'd to 500 psi, held OK. POH w/pact 09-08-94 thru 09-12-94 Ran cup-type R testing csg while coming up hole. The for 1705'. Interval 1705-1076' did not hold 1201' and 1201-1139' tested OK. Leaked 1 BPM. Still have another hole above 11 w/retrieving head. Washed and circ'd sc OK. Set packer at 1076'. Press'd to 500 leaked. Reset packer at 669', tested OK. Latched RBP. POH w/tbg, packer and R 	Recomptetion Plugging Back Cating Repair Alaring Cating Alaring Cating Solate casing So	New Construction Non-Routuse Fracturing Water Shut-Off Conversion to Injection I teak I teak Outpose Water (Non: Report results of multiple completions on Weil Completion of Recompletion Argon and Leg term. date of starting any proposed work. If well is directionally drail as bad. LD all tbg. Ran 6 1/4" bit on 2 7/8" g to 500 psi but did not hold press. Reset of these settings. Reset packer at 508', on Early. Tested RBP to 1000 psi, held OK. Began 5266-2954', 2954-2644', 2644-2330', 2330-10 500 psi, held OK. The intervals 1389-10 annulus, would not hold press test at ad fill on RBP. TOH, removed packer. TIH 07' and reset. Tested RBP to 1000 psi, held 10 500 psi, held OK. Reset packer at 638', in 650-669'. Ran packer and retrieving head. rods in singles. LD 106 jts 2 7/8" tbg (work CEP' and Factor and retrieving head. I 8 199

"See instruction on Reverse Side

٠