

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN PLICATE\*  
(Other Inst. on re-verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0560355

6. IF INDIAN, ALLOTTED OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> JAN 2 1968		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Ernest A. Hanson		8. FARM OR LEASE NAME Payne Federal "A"	
3. ADDRESS OF OPERATOR P. O. Box 1515, Roswell, New Mexico		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FSL & 1800' FEL Sec. 6, T-19-S, R-31-E, N.M.P.M. Eddy County, New Mexico		10. FIELD AND POOL, OR WILDCAT Shugart - Queen	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 6 - 19S - 31E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3537' DF		12. COUNTY OR PARISH Eddy	
		13. STATE N. Mex.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

T.D. @ 3310' P.B.T.D. @ 3298' Perfs. @ 3212-3263' Top Salt @ 790'  
8-5/8" @ 200' w/50 sx. 5-1/2" @ 3299' w/150 sx.

The captioned well was plugged and abandoned effective November 1, 1967, in the following manner:

1. The hole was displaced with heavy mud.
2. A 20 sx. cement plug was spotted across the perfs. @ 3127-3298'.
3. Set nitro shots at 1550', 1525' and 1500' and could not pull casing.
4. Shot casing at 1474' and pulled.
5. A 20 sx. cement plug was spotted @ 1575' in-and-out of 5-1/2" casing.
6. A 20 sx. cement plug was spotted @ 756-824' @ Top of Salt
7. A 20 sx. cement plug was spotted @ 167-214' in-and-out of 8-5/8" casing.
8. A 10 sx. cement plug was spotted at the surface and a regulation dry-hole marker erected.
9. The location was cleaned-up and made ready for final inspection by the U.S.G.S.

18. I hereby certify that the foregoing is true and correct

SIGNED Harry L. Schumacher TITLE Exploration Manager DATE Dec. 8, 1967

(This space for Federal or State office use)

APPROVED BY John C. Brant TITLE DISTRICT ENGINEER DATE 12 11 1967

CONDITIONS OF APPROVAL, IF ANY: