

(SUBMIT IN TRIPPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. 06309-A

Unit A

RECEIVED

OCT 8 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	ARTESIA, OFFICE
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 1, 1963

Runyan Ranch Unit

Well No. 1 is located 660 ft. from [N] line and 910 ft. from [E] line of sec. 12

NE/4 Section 12  
(1/4 Sec. and Sec. No.)

T-19-S  
(Twp.)

R-21-E  
(Range)

NMPM  
(Meridian)

Wildcat  
(Field)

Eddy

(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs; cementing points, and all other important proposed work.)

Spudded well 9-20-63. Set new 13 3/8" 48# H-40 casing at 172 feet and cemented with 200 sacks cement. Cement circulated 9-21-63. WOC 12 hours. Pressure tested casing to 600 psi for 30 minutes. Held pressure. 9-21-63. Set new 9 5/8" 32, 30# H-40 at 1816 feet and cemented with 1060 sacks cement. Top cement approximately 400 feet. 9-26-63. Ran 1" pipe outside 9 5/8" casing to 360 feet. Cemented with 200 sacks. Ran 1" pipe to 120 feet and cemented with 75 sacks. 9-26-63. Hole in casing at 152 feet. Squeezed with 245 sacks cement 9-28, 29 and 30, 1963. Tested casing to 1000 psi for 30 minutes 9-30-63. Held pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tom Brown Drilling Company, Inc.

Address %Albritton & Meyer

P.O. Box 524, Midland, Texas

By \_\_\_\_\_

Title Agent

