## N.M. Ca Cons. Division 811 S. ist Street

m 3160-5 ne 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Artesia,	NM	FORM APPROVED  882#@12899. 1004-0135 Expires: March 31, 1993
. x ~ /		

Lease	Desig	nation	and	Senal	
	373.6	0/5	10		

SUMBRY MOTICES	AND REPORTS ON WELLS	NM-04560			
Do not use this form for proposals to dr	ill or to deepen or reentry to a different reservoir R PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name			
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation			
1. Type of Well Oil Well Well Other	(199 <b>782)</b>	8. Well Name and No.			
2. Name of Operator		Pecos River Deep Unit #1			
Yates Drilling Company		9. API Well No.			
3. Address and Telephone No. 105 S. 4th St., Artesia,		30-015-10051 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey D	escription)	McMillan Morrow North			
1980' FNL & 1980' FWL		11. County or Parish, State			
Section 28-198-27E		Eddy County, NM			
12. CHECK APPROPRIATE BOX	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	Abandonment	Change of Plans			
	Recompletion	New Construction			
Subsequent Report	Plugging Back	Non-Routine Fracturing			
	Casing Repair	Water Shut-Off			
Final Abandonment Notice	Altering Casing	Conversion to Injection			
	🛛 <sub>Other</sub> Reperforate & Return	Dispose Water			
	to production	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
<ol> <li>Describe Proposed or Completed Operations (Clearly state a)</li> </ol>	I pertinent details and give pertinent dates including estimated date of service				

- give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
  - Rig up workover unit and kill well, if necessary.
  - ND tree and NU BOP, unseat packer and POH with tubing.
  - RIH with bit and scrapper, circulate hole clean.
  - RIH with 4" perforating guns and reperforate lower morrow. 4.
  - RIH with packer and new 2 3/8" N-80 tubing, set packer and pump packer fluid. Test backside to 1000 psig.
  - RU service company and pump Nitrified acid job. Flow well back and produce well.

