 Submit 3 Copies to Appropriate District Office 	State of Ener			=15[form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505				WELL API NO 30-015-10110	
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe,	NM 87	(505	sIndicate Type of Lea	ase
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				«State Oil & Gas Lea	STATE FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7Lease Name or Unit Agreement Name East Millman Unit	
• Туре of Well: OIL GAS WELL / WELL OTHER WIW					
aName of Operator V SDX Resources, Inc.				*Well No. 189	
3Address of Operator PO Box 5061, Midland, TX 79704				Pool name or Wildcat Millman Yts-7R (46555)	
•Well Location Unit Letter M 330) Feet From The Sout	th	Line and 990	Feet From The	West Line
Section 11			tange 28E	NMPM	Eddy County
toElevation (Show whether DF, RKB, RT, GR, etc.					
¹¹ Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING
	MPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING C				
PULL OR ALTER CASING		_	CASING TEST AND CEME	INT JOB	
OTHER: Repair csg.			OTHER:		
¹² Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Flow back well & TOH w/PC tbg & pkr					
TIH w/bit on 2-3/8" workstring & clean out well to 2230'					
Set RBP @ 1760' & test w/pkr for hole. Depending on results will either squeeze hole or attempt to back off & replace top portion of 4-1/2" csg.					
Csg. Once csg tests ok - pull RBP & LD workstring Run AD-1 back to 1756' on 2-3/8" PC & return well to injection.					
Run AD-1 back to 1756' on 2-3/8" PC & return well to injection.					
				CD ARTED	192021
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE Mong TITLE Engineer DATE 02-10-00					
					TELEPHONE NO.
(This space for State Use)					
APPROVED BY MEASSTUPPE	٩	TIT	TLE Field Rep. IF		DATE 2/24/2000
* Notifie NAUCA to Witness Repair operations					

EMU # 189 330 FSL & 990'FWL Sec. 11 T19S R28E Edy Co., N.M.

Existing Condition: 12-1/2" hole to 452' with 452' of 10-3/4" csg cemented with 100 sxs. 8" to 2264 with 2264' of 4-1/2" casing cemented with 200 sxs. (TOC by lof at 420'). Perfs: 1798'-2206'. 2-3/8" PC tubing at 1756' with baker AD-1.

Proposal:

1.) Flow back well and TOH with PC tubing and packer.

,

- 2.) TIH with bit on 2-3/8" workstring and clean out well to 2230'.
- 3.) Set RBP at ~ 1760' and test with packer for hole. Depending on results will either squeeze hole or attempt to back off and replace top portion of 4---1/2" casing.
- 4.) Once casing test OK: pull RBP and lay down workstring.
- 5.) Run AD-1 back to 1756 on 2-3/8" PC and return well to production. injection.