

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

CISF
OP

WELL API NO. 30-015-10188
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name State 648
Well No. 193
Pool name or Wildcat Millman YT-7R-QN-GB, East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
Name of Operator SDX Resources, Inc. /	
Address of Operator PO Box 5061, Midland, TX 79704	
Well Location Unit Letter <u>K</u> <u>1750</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>West</u> Line Section <u>22</u> Township <u>19S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Current Csg Condition:

10-3/4" @ 225' w/75 sx. TOC Cadl @ surf
4-1/2" @ 2217' w/325 sx.
Perfs: 1746' - 2097'

Propose to P&A as follows:

3
Set CIBP @ 1700' & cap w/3 sx cmt. Circ hole w/mud laden fl. Cut & pull 4-1/2" from 850' if possible.
Spot 25 sx plug 900' - 800' Tag 100' Plug 500' to 600'
Spot 50 sx plug 275' - 175' Tag
Spot 10 sx surface plug.

25
Install marker & clean location.

Give OED 24 hrs notice Prior to Any work

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Atwater TITLE Regulatory Tech DATE 09-06-01

TYPE OR PRINT NAME Bonnie Atwater TELEPHONE NO. 915/685-1761

(This space for State Use)

APPROVED BY [Signature] TITLE John H. TD DATE 9-19-01

CONDITIONS OF APPROVAL, IF ANY: