

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
RECEIVED BY BOX 2018
SANTA FE, NEW MEXICO 87501
AUG 30 1985
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
E-7345

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement No.
2. Name of Operator ARROWHEAD OIL CORPORATION	8. Farm or Lease Name MACHRIS STATE
3. Address of Operator P.O. BOX 548, ARTESIA, NEW MEXICO 88210	9. Well No. 1
4. Location of Well UNIT LETTER A 330 FEET FROM THE North LINE AND 970 FEET FROM East 32 TOWNSHIP 19-South RANGE 31-East NMPM.	10. Field and Pool, or Whichever Hackberry Yates SR North
15. Elevation (Show whether DF, RT, GR, etc.) 3483' RT	12. County EDDY

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUGGED & ABANDONED:

Set 50' plug thru open hole-2263'-2213', tagged-o.k.
Run in hole with free point-estimated free point @ 1910'.
Shot casing off @ 1902'- pulled csg. run in hole w/tbg.
Set cement plug @ 1950'- 1850', tagged-o.k.
Ran in hole w/tbg. to 1800', circulated cement to surface.
Installed dry hole marker.

Post FD-2
9-6-85
PVA

Will notify when location is cleaned & ready for inspection.

VERBAL APPROVAL BY: MIKE WILLIAMS

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Shirley Lopez</u>	TITLE <u>Production Clerk</u>	DATE <u>8/27/85</u>
APPROVED BY <u>Danell Moore</u>	TITLE <u>Geologist</u>	DATE <u>3/27/86</u>

CONDITIONS OF APPROVAL, IF ANY: