

Submit 3 Copies to Appropriate

District Office

DISTRICT I

1625 n. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

2040 S. Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

RECEIVED
OCD - ARTESIA

Form C-103

Revised March 25, 1999

WELL NO.

30-015-10352

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

State A

8. Well No.

2

9. Pool name or Wildcat Millman;
Yates-SR-QN-GB-SA-East

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator

Louis Dreyfus Natural Gas Corp.

3. Address of Operator

14000 Quail Springs Parkway - Suite 600 - Oklahoma City, OK 73134

4. Well Location

Unit letter D; 330' feet from the North line and 330' feet from the West line.

Section 24 Township 19S Range 28E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, Gr, etc.)

3368'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE
COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND
ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set CIBP @ 2,100', cement w/ 3" sx cement.

2. 30 sx plug @ 1500'. Perf. csy @ 729' squeeze 100' of ant. inside: outside csy. 629'-729' - Tag

3. 50 sx plug @ 448'-248'. Perf. csy @ 350' squeeze 100' of ant. inside: outside csy. 250'-350' - Tag

4. 30 sx plug @ 3'-33'. Perf. csy @ 60' Circ. csy. with cmt. inside: outside 0-60'

5. Cap well, cut anchors, clean location.

Install marker

Notify OCD 24 hrs. prior to any work done

Salt gel mud consisting of 10#
Brine W/25# of gel per bbl
must be placed between each plug

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Carla Christian

TITLE

Regulatory Technician

DATE

02/19/02

Type or print name

Carla Christian

Telephone No.

405-749-5263

(This space for State use)

APPROVED BY

[Signature]

TITLE

Wild Sep ID

DATE

MAR 1 2002

Conditions of approval, if any: