# RECEIVED

DRILLING PROGROSIS Barton Federal No. 2 Page Three

# FEB 1 0 1965

O. C. C. ARTESIA, DEFICE

#### DRILLING TING:

- 1. A recorder with torque, hook load and rate of penetration will be used.
- 2. Record 10' drilling times from surface to T.D. on company forms.

DRILL PIPE MEASUREMENTS: Strap drill pipe at all casing, testing, coring, logging, points and at T.D.

### DRILLING SAMPLES:

- 1. Two sets of 10' samples will be caught, washed, sacked, and labeled in bundles of 100' from surface to T.D.
- 2. Circulating and additional samples will be obtained as directed.
- 3. Quart samples will be obtained of all fluids recovered on DST.

#### COEES: None Anticipated

DRILL STEM TESTING: Tests to be taken at direction of wellsite geologist.

#### LOGGING:

- 1. Gamma Ray Sonic Caliper from T.D. to base of intermediate casing.
- 2. Dual induction-laterolog through sections as specified by wellsite geologist.

#### BLOW OUT PREVENTORS:

- 1. Series 900 or better, double ram with manual and remote control preventors shall be used from base of surface to T.D.
- 2. BOP shall be checked daily and reported on drilling report.
- 3. A rotating drilling head shall be used during any air or gas drilling.

# DAILY DRILLING REPORTS:

- 1. The AAODC report will be used.
- 2. This report will be filled out in detail and mailed to Midland District Office four times per week.
- 3. Morning reports shall be made to the Midland District Office each week-day morning between 8:00 a.m. and 8:30 a.m., C92
- 4. The company forms for daily drilling report and daily cost report will be prepared each day and delivered to the drilling section at the end of each well.

# DEVIATION:

- 1. Deviation in the surface hole shall not exceed 1°.
- 2. Deviation surveys shall be taken on every trip or every 500°, whichever is first.