

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI-STATE
(Other instructions on re-verse side)

FORM APPROVED
Budget Bureau No. 48-R1494

5. LEASE DESIGNATION AND SERIAL NO.
LC 063696

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Barton Federal

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Lusk Strawn

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
Sec. 22, T19S, R31E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER P & A

2. NAME OF OPERATOR
Tenneco Oil Company ✓

3. ADDRESS OF OPERATOR
Suite 1200 - Lincoln Tower Bldg. - Denver, Colo

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
660' F/SL and 660' F/EL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3501 GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	
(Other) _____			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well plugged and abandoned as follows: Shot & pulled 4 1/2" casing from 7556', 8-5/8" casing from 931' and pulled 11,174' of 2-3/8" tubing. CIBP set @ 11150' capped W/35 sks cement. Cement plugs installed as follows:

DEPTH

<u>From</u>	<u>To</u>	<u>No. of Sacks</u>
7606	7506	30 @ 4 1/2" csq. stub
6980	6880	50 sks
5500	5400	50
4015	3915	35 across 8-5/8" csq. shoe
981	881	50 sks in & out of 8-5/8" csq. stub
760	660	47 sks across 13 3/8" csq. shoe
Surface		10 sks

Installed dry hole marker & cleaned location

18. I hereby certify that the foregoing is true and correct

SIGNED S. A. Ford TITLE Sr. Production Clerk DATE 8-15-72

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APR 29 1973
A. J. Beckman

*See Instructions on Reverse Side