

OIL CONSERVATION DIVISION

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

SANTA FE, NEW MEXICO 87501

JUN 29 1987

O. C. D.

ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-8949	
7. Unit Agreement Name Turkey Track Sec 3 Ut.	
8. Farm or Lease Name Turkey Track Sec. 3 Ut.	
9. Well No. 6	
10. Field and Pool, or WHDCat	
12. County Eddy	

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- <input type="checkbox"/>
Name of Operator Marbob Energy Corporation		
Address of Operator P.O. Drawer 217, Artesia, N.M. 88210		
Location of Well UNIT LETTER <u>F</u> , <u>2635</u> FEET FROM THE <u>North</u> LINE AND <u>1325</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>19S</u> RANGE <u>29 E</u> NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.)

3394' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandon as follows:

Pump 35 sx plug @ 2150', tagged @ 1550', set 10 sx plug @ 1300', perf 2 holes @ 1020', set packer @ 900', pump 45 sx in and out of casing, tagged @ 860', perf 2 holes @ 420', set retainer @ 380', circ cement in and out of casing. Installed dry hole marker and cleaned location.

Part 10-2
7-10-87
P4A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

PROVED BY Rhonda Nelson TITLE Production Clerk DATE June 25, 1987

PROVED BY Daniel Moore TITLE Geologist DATE 12/3/87

CONDITIONS OF APPROVAL, IF ANY: