

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-029387 (d)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

21 Desta Drive, Midland, Texas 79705

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

830' FWL & 1650' FSL, Sec. 19, T-18-S, R-31-E

RECEIVED BY

MAR 02 1984

O. C. D.

AMERICA OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Kenwood Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Shugart (Y, SR, O, G)

11. SEC., T., S., M., OR BLK. AND
SURVEY OR AREA

Sec. 19, T-18-S, R-31-E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3628' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. MIRUPU. Unload 2 7/8" work string. Install BOP.
2. RIH w/4 3/4" bit to bridge @ 1620'. Clean out bridges & fill to \pm 3200'.
3. Call NMOC & Dept of Interior in Artesia. P&A as follows:

- a. Spot 100' cmt plug 3150-3050' (above Queen zone). Tag TOC plug. Spot mud to + 1900'.
- b. Spot 100' cmt plug 1900-1800' (below salt). Tag TOC plug. Spot mud to + 850'.
- c. Spot 100' cmt plug in ~~8 5/8"~~ of the 8 5/8" csg shoe @ 772' (or ~~822'~~).
- d. Spot 50' cmt plug @ surf. Weld on plate & install marker.

4. RDPU. Clean location. Fill in pits.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Engineer

DATE 1/26/84

(This space for Federal or State office use)

APPROVED BY PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

FEB 29 1984

*See Instructions on Reverse Side

RECEIVED

JAN 31 10 13 AM '84

BUR. OF LAND MGMT.
ROSKILL, N.Y.