State "BE" #1 (Tests continued) 9-198=28E Eddy County, N.M. (Hondo Oil & Gas Co.)

DST #11 (Strawn) 10150-10225, 3/4" BC, 1" TC, no WC. Took 5" preflow w/weak air blow throughout. Took 75" ISI. Tool open 2 hrs w/weak air blow throughout. Took 75" FSI, unable to pull pkrs loose. Jarred on pkrs 3-1/2 hrs w/30,000# & jars stopped working. While attempting to release safety jt, opened secondary reverse sub, equalizing mud IL csg annulus & DP. Recovered top 1/2 of safety jt, upper pressure bomb from DST #11 & hydraulic test tool. No shows of oil or gas in mud trapped in DP.

75*	TRL=2780#	FFP=134
	ISI <b>P=</b> 5186#	<b>F</b> S I <b>P=7</b> 87#
	I <b>FP=9</b> #	PHP=5186#

## RECEIVED

## AUG 2 1 1209

In the state of t

చెంచడితో సమీప ఉందిని సారా సారాలు సంగారం కార్లక్ర సాజమీపడు మూట్లై శాశిశముల్లు రాజుగులై ప్రాణాణింగ ప్రస్తున్న స్టార్

<u>الله المحمد الم المحمد الم المحمد الم المحمد الم المحمد المحم المحمد المحم المحمد ا المحمد المحم المحمد المحم المحمد المحم المحمد المحم المحمد المحمد المحمد المحمد المحمد المحمد المحمد المحم المحمد المحم المحمد المحم المحمد المحمد المحمد المحمد المحمد المحمد</u>

e de la fili	
	and and a star

## RECEIVED

## 

. . .