

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	/
FILE	/-
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
648	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - <b>P &amp; A</b>		7. Unit Agreement Name
2. Name of Operator <b>Hondo Oil &amp; Gas Company</b>		8. Farm or Lease Name <b>State "BE"</b>
3. Address of Operator <b>P. O. Box 1978, Roswell, New Mexico</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>K</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>9</b> TOWNSHIP <b>19-S</b> RANGE <b>28-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat</b> <i>Planned (Strawn)</i>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3565' DF</b>		12. County <b>Eddy</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled (8-3/4" hole) to a T.D. of 11,227' without encountering commercial hydrocarbons. The well was plugged & abandoned by setting the following neat Incor cement plugs:

65 sx from 10960-11190	30 sx from 7545-7645
30 sx from 10592-10692	30 sx from 6041-6141
65 sx from 10225-10317	30 sx from 3284-3384
30 sx from 9895-9995	40 sx from 2438-2538
30 sx from 9331-9431	10 sx in top of well.

9.8#/gal. gel mud was used to spot all plugs. 13-3/8" & 9-5/8" casing strings were left intact. A dry hole marker was erected. We will notify your office by letter when this location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed

SIGNED A. D. Kloxin

TITLE Dist. Drlg. & Prod. Supt. DATE 8-23-66

APPROVED BY W. A. Gussert

TITLE OIL AND GAS INSPECTOR

DATE SEP 21 1966

CONDITIONS OF APPROVAL, IF ANY: