N.M.O.C.D. COPY	Form Approved.	
rm 9–331	Budget Bulese Hole /2	×.
UNITED STATES	5. LEASE NM-032240	•
DEPARTMENT OF THE INTERIOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
GEOLOGICAL SURVEY	RECEIVED	
	7. UNIT AGREEMENT NAME	
SUNDRY NOTICES AND REPORTS ON WELLS to not use this form for proposals to drill or to deepen or plug back to a different the form 9-331-C for such proposals.)	8. FARM OR LEASE NAME JUN 2 6 1981	h
is not use this form for proposals to ornorals.)		
1. oil gas	9. WELL NO.	
well well other	9. WELL NO. ARTESIA, OFFICE	
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME	•
Dorchester Gas Corporation / 3. ADDRESS OF OPERATOR	Lusk Strawn	
D O DOW OF HOUDS, New Mexico 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	28-T19S-R31E	
below.)	12. COUNTY OR PARISH 13. STATE	
AT SURFACE: 660' FSL & 660' FEL AT TOP PROD. INTERVAL:	Lea Eddy New Mexico	-
AT TOTAL DEPTH:	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-015-10848	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3469.2 GL	
STATE PERCET	3469.2 GL	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
FRACTURE TREAT		
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASING	change on Form 9-330.)	
MULTIPLE COMPLETE		
CHANGE ZONES		
		\$
ABANDON*		1
	tate all pertinent details, and give pertinent dates, s directionally drilled, give subsurface locations and nent to this work.)*	ş
 ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertire 	another T&A well in this pool	2
ABANDON*	another T&A well in this pool will be temporarily abandoned quence with operator's other wells	
 ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertires Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well is the propose to pull tubing the tested in section. 	another T&A well in this pool will be temporarily abandoned quence with operator's other wells	20 20
 ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertires Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well is the propose to pull tubing the tested in section. 	another T&A well in this pool will be temporarily abandoned quence with operator's other wells	
 ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertires Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in see in this field to determine potential for the second sec	another T&A well in this pool will be temporarily abandoned quence with operator's other wells	
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for the second This approval of temporary	another T&A well in this pool will be temporarily abandoned quence with operator's other wells	
 ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertire Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in see in this field to determine potential for the second second	another T&A well in this pool will be temporarily abandoned quence with operator's other wells	
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for the second This approval of temporary	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion.	
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for This approval of temporary abandonment expires	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion.	20
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for This approval of temporary abandonment expires	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion.	
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for This approval of temporary abandonment expires. Subsurface Safety Valve: Manu. and Type	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion. $\frac{124/82}{5000000000000000000000000000000000000$	
ABANDON* (other) TempOrarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for This approval of temporary abandonment expires. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED. Market Market Mar	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion. JUN 17 1981 JUN 17 1981 JUN 17 1981 Set @Ft. JUN 15, 1981	2 2
ABANDON* (other) TempOrarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for This approval of temporary abandonment expires. Subsurface Safety Valve: Manu. and Type	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion. JUN 17 1981 JUN 17 1981 JUN 17 1981 Set @Ft. JUN 15, 1981	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in see in this field to determine potential for This approval of temporary abandonment expires. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct SIGNED	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion. JUN 17 1981 JUN 17 1981 JUN 17 1981 Set @Ft. JUN 15, 1981	n and a second
ABANDON* (other) TempOrarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for This approval of temporary abandonment expires. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED. Market Market Mar	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion. JUN 17 1981 JUN 17 1981 JUN 17 1981 Set @Ft. DATEJUNE 15, 1981	
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in see in this field to determine potential for This approval of temporary abandonment expires. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct SIGNED	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion. JUN 17 1981 JUN 17 1981 JUN 17 1981 Societ A GAL Societ Marsurey F Societ Marsurey	
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in sec in this field to determine potential for This approval of temporary abandonment expires. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct SIGNED	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion. JUN 17 1981 JUN 17 1981 GRA GAL Set @Ft. DATE JUN 2 4 1981	
ABANDON* (other) Temporarily Abandon 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertir Propose to pull tubing for use in testing (Plains Operating Area No. 6). This well until such time as it can be tested in see in this field to determine potential for This approval of temporary abandonment expires. Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED	another T&A well in this pool will be temporarily abandoned quence with operator's other wells recompletion. JUN 17 1981 JUN 17 1981 GRA GAL Set @Ft. DATE JUN 2 4 1981	