

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug and Abandon		7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL COMPANY		8. Farm or Lease Name Buchanan Gas Com.
3. Address of Operator P.O. Box 1069 - Hobbs, New Mexico		9. Well No. 1
4. Location of Well UNIT LETTER F , 1650 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 20-S RANGE 25-E NMPM.		10. Field and Pool, or Wildcat Dagger Draw Morrow Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3530' GR		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We proposed to plug and abandon this well as follows:

1. Set 50 sks. cement 9355-9255'
2. Set 50 sks. cement 8750-8650'
3. Set 50 sks. cement 7830-7730'
4. Set 50 sks. cement 5675-5575'
5. Set 50 sks. cement 2200-2100'
6. Set 75 sks. cement 1300-1200'
7. Set 10 sks. cement at surface.
8. Install dry hole marker.

RECEIVED

NOV 9 1966

N. C. C.
ARTESIA, OFFICE

Verbal approval granted per telephone conversation with Bill Gressett on 11-2-66 to begin plugging operations on above well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u><i>William A. Gressett</i></u>	TITLE <u>Area Superintendent</u>	DATE <u>11-3-66</u>
APPROVED BY <u><i>W. A. Gressett</i></u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>NOV 9 1966</u>
CONDITIONS OF APPROVAL, IF ANY:		