

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | 7 |
| DISTRIBUTION | |
| SANTA FE | 1 |
| FILE | 1 |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | 5 |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| | |
|--|---|
| 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> | |
| 5. State Oil & Gas Lease No. OG 272 | |
| SUNDY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small> | |
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- | 7. Unit Agreement Name N/A |
| 2. Name of Operator SOUTHWEST PRODUCTION CORPORATION | 8. Farm or Lease Name LOWE STATE |
| 3. Address of Operator P.O. Box 1464 Midland Texas - P.O. BOX 936 - ROSWELL, NEW MEXICO 88201 | 9. Well No. 2 |
| 4. Location of Well UNIT LETTER "H" 1980' FEET FROM THE North LINE AND 990' FEET FROM THE EAST LINE, SECTION 11 TOWNSHIP 19S RANGE 28E NMPM. | 10. Field and Pool, or Wildcat E. Millman G. No. |
| 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County EDDY |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|---|---|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/> |
|---|---|--|---|

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to shoot 4½" casing at 1450' and pull same.

Place fifty (50) sacks of cement plug - 2235' - 1800'
(Top perforation 1840')

Place fifteen (15) sacks of cement plug in bottom of surface casing - 640' to 580'.

Place ten (10) sacks cement plug in top and install dry hole marker.

Level and clean location.

RECEIVED

JUL 12 1967

D. H. G.
ARTIFICIAL CHARGE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter Clements, Jr. TITLE MANAGER DATE 7/12/67

WALTER CLEMENTS, JR.

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE JUL 13 1967

CONDITIONS OF APPROVAL, IF ANY:

Intervals between plugs filled w/ mud
100' plug at stub of 4½" casing
100' " " base of surface casing @ 590-690