

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-1230 1231/232	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator CARL ENGWALL & JAMES R. STEPHENS		8. Farm or Lease Name Gulf-State
3. Address of Operator P. O. Box 789, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 19S RANGE 31E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3546 RT		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

August 21, 1967 - plugs at 11,000' 30 sacks, 10,050' 30 sacks,
6,760' 30 sacks, 4,222' 30 sacks

August 22, 1967 - Cut 7" Casing at 2590' and pulled 78½ joints
Plugs at 2500' 30 sacks, surface 10 sacks aground marker

Casing left in Hole - 13-3/8" - surface to 655'
8-5/8" - surface to 3820'
7' - 2590' to 4227'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Carl Engwall</u>	TITLE <u>Operator</u>	DATE <u>8-25-67</u>
APPROVED BY <u>J. F. Kamm</u>	TITLE <u></u>	DATE <u>8-27-67</u>
CONDITIONS OF APPROVAL, IF ANY:		