

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-20114
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Nicholas BJ
8. Well No. 1
9. Pool name or Wildcat Penasco Draw-SA-Yeso
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3563' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P&A
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210 (505) 748-1471
4. Well Location Unit Letter I : 2310 Feet From The South Line and 330 Feet From The East Line Section 5 Township 19S Range 25E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3563' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Plugged well as follows: POH with tubing. Lay down perf sub and mud joint. RIH w/tubing to 1550'. Spotted 40 sx cement. Tagged cement at 1238'. Spotted 10 sx cement at 1238'. Brought up to 1098'. Dug out cellar, no 7" casinghead on well. RU perf-shots and perf'd casing at 365'. Ran 1 jt tubing and packed off wellhead. Pump 30 bbls water. Did not break circulation to surface. RIH with tubing to 420'. Spotted 25 sx cement. WOC. Ran tubing to 1078'. Tagged first plug. Laid down 1 joint. RU pump. Spotted 56 sx cement w/10% Calcium. POH w/tubing and WOC. RIH and tagged plug at 375'. RU shot can. RD floor and tubing tongs. ND 4 1/2" wellhead. Screwed on 4 1/2" pull nipple. Free point casing - show free at 600'. RIH w/shot can. Casing at 345'. RD tubing equipment. RU casing equipment. Laid down 11 jts 4 1/2" casing. RD casing equipment. RU 2-3/8" tubing equipment. RIH w/tubing to 350'. Spotted 50 sx cement plug w/2% CaCl2. POH w/tubing. RIH w/tubing. Did not tag cement plug. Re-spot plug w/50 sx cement at 350'. POH w/tubing and WOC. RIH w/wireline. Did not tag cement plug. Ray Smith, NMOCD, Artesia, approved spotting 6 yds gravel and filled up to 240'. Circulated 72 sacks. POOH w/tubing. Set P&A marker. Witnessed by Gary Williams, NMOCD, Artesia. P&A COMPLETED 3-7-94

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-10-94
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Michael Stubblefield TITLE Field Rep. I DATE Sept. 21-94
CONDITIONS OF APPROVAL, IF ANY:

Post ID-2
4-1-94
P&A