

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Wildcat - dry hole		7. Unit Agreement Name
2. Name of Operator H. T. Hilliard		8. Farm or Lease Name Foster Ranch
3. Address of Operator 418 Bank of Southwest, Midland, Texas		9. Well No. 1
4. Location of Well UNIT LETTER K, 2220 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 22 TOWNSHIP 20-S RANGE 24-E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3695 GL 3707 KB		12. County Eddy

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Drilled 7-7/8" hole to 9313' on 4-24-68  
Spotted cement plugs as follows:  
30 sx. Trinity Lite Wate at 9157-9267  
30 sx. " " " at 8940-9050  
30 sx. " " " at 7500-7610  
30 sx. " " " at 6005-6115  
Set 130 sx. Incor. Neat 5605-5460' for DST plug. Drilled out to 5486'.  
Set 100 sx. Class H Neat 5218-5486'. Drilled out at 5450'  
Set 30 sx. Trinity Lite Wate at 5300-5400.  
Set 30 sx. Trinity Lite Wate at 3140-3250  
Set 40 sx. Class H Neat across base of 8-5/8 from 980' - 1100'. P & A completed 2 p.m. 4-30-68.  
Capped well - turned well over to Loyd Foster P. O. Box 268, Artesia, New Mexico

RECEIVED  
MAY 8 1968  
O. G. C.  
ARTESIA OFFICE

### 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. B. Taylor</u>	TITLE <u>Engineer</u>	DATE <u>May 2, 1968</u>
APPROVED BY <u>R. L. Ham</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>JUL 23 1968</u>
CONDITIONS OF APPROVAL, IF ANY:		