

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
BMD60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER RECOMPLETION		2. NAME OF OPERATOR YATES PETROLEUM CORPORATION		3a. Area Code & Phone No. 505/748-1471		5. LEASE DESIGNATION AND SERIAL NO. NM 045274	
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 1980' FWL, Sec. 23-T20S-R24E		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A		7. UNIT AGREEMENT NAME N/A	
14. PERMIT NO. 30-015-20426		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3682' GR		8. FARM OR LEASE NAME Hill View AHE Federal Com		9. WELL NO. 3	
				10. FIELD AND POOL, OR WILDCAT South Dagger Draw Upper Penn		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Associated Unit N, Sec. 23-20S-24E	
				12. COUNTY OR PARISH Eddy		13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) Perforate

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-31-90. RUPU. POOH with RBP and packer. WIH and washed frac, ball sealers, and sand from 6900' to 7600'. Cleaned off top of RBP. Latched onto RBP @7600'. TOH with RBP and tubing. TIH with packer to 7600'.
8-3-90. Acidized existing perforations 7696-7800' w/23000 gals 20% NEFE acid and scale inhibitor in 3 stages with 1500# block between each stage. TOOH with packer. Perforated 12 - .50" holes 7655-7666' (1 SPF). Acidized perms 7655-7666' w/3000 gals 20% NEFE acid. Moved tools and straddled perms 7655-7800'. Swabbed load to recover.
8-8-90. Set sub pump.
8-9-90. First production.

18. I hereby certify that the foregoing is true and correct

SIGNED *Jamesita Sandoval*

TITLE Production Supvr.

DATE 8-29-90

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side