

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

FEB 11 1972

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	L-3355

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator The Petroleum Corporation	8. Farm or Lease Name Petco State Com
3. Address of Operator 3303 Lee Parkway, Dallas, Texas 75219	9. Well No. 2
4. Location of Well UNIT LETTER N, 660 FEET FROM THE S LINE AND 1980 FEET FROM THE W LINE, SECTION 26 TOWNSHIP 12 RANGE 29 Eddy NMPM.	10. Field and Pool, or Wildcat Parkway Volcano
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Load hole with gel mud.
2. 25 sack plug, across perforations 9622-40
3. 35 sack plug, at) approx. 7000'
4. Cut off 4 1/2" casing)
5. 35 sack plug at 5660' 3850
6. 35 sack plug at bottom of 8-5/8" at 3800'
7. 35 sack plug at cutoff of 8-5/8"
8. 35 sack plug at 600'. 640
9. 10 sack plug at surface.
10. Install dry hole marker.

Work to begin 2-10-72.

Csg 11 3/4" - 605 - 600
8 3/8" - 3860 - 700
4 1/2" - 9174 - 360

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chas. Baker TITLE President DATE 2-10-72

APPROVED BY W.A. Gussert TITLE W.S. DATE FEB 11 1972

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.O. in sufficient time to witness

Plugging operations