

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Albuquerque, NM 88210

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

4SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen an oil well or to plug back an oil well or to plug back a gas well.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Shut-in

2. NAME OF OPERATOR CONOCO INC.

3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface Unit H

14. PERMIT NO. 30-015-20441

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3000 SC

5. LEASE DESIGNATION AND SERIAL NO.
NM-13720

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Barbara Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
No. Dagger Draw Penn

11. SEC., T., R., M., OR B.L.E. AND SURVEY OF AREA
Sec. 18-19S-25E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☒
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU. POOH w/ 4bg
- ② Spot 25 sxs class "H" on top of cement retainer @ 766' (cmt from 766'-746')
- ③ Spot 19 sxs class "H" from 5375'-5325'. Perf @ 2015' w/ 4 JS PF. Set cm retainer @ 2005'. Try to establish pump-in rate.
- ④ If pump-in rate is established and cannot circ. to surface, pump 55 sxs class "H" below ret @ 2005' and spot 14 sxs on top of ret.
- ⑤ If circ. to surface is possible, pump 436 sxs class "H" and circ to surface. Spot 14 sxs cmt on top of retainer. Spot 13 sxs class "H" from 1020'-1120' seal of int. csg shoe
- ⑥ Spot 13 sxs class "H" from 370'-470' to seal off surf. csg shoe.
- ⑦ Spot 50' surface plug. Cut off csg 3' below final ground level. Install P & A marker. Rig down
- ⑧ A P & A sketch is attached.

18. I hereby certify that the foregoing is true and correct

SIGNED Carl O. Gaudin TITLE Administrative Supervisor DATE 7-16-86

(This space for Federal or State office use)

APPROVED BY David Adams TITLE Acting DATE 7-22-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Barbara Federal No. 1(Zero @ 15' AGL) Abandonment Marker
51-65' Cap

Location: 1980' FNL, 660' FEL

Section 18, T-19S, R-25E

Eddy County, New Mexico

Elevation: 3564' DE (15' AGL)

TD: 9040' ; PBTD: 8191' (Float Collar)

370'-470' Plug

425' ; $12 \frac{3}{4}"$, 32 #/ft Csg w/ 400 SX Circ.

1020'-1120' Plug

1070' ; $8 \frac{5}{8}"$, 24 #/ft Csg w/ 725 SX Circ.

1900'-2005' Cap

2005' Cement Retainer

San Andres 1965'
Glorieta

2015' Perfs (4spf)

5375'-5525' Plug

5240' TOL

Abo 5450'
Wolfcamp

7461'-7661' Cap

7661' Cement Retainer

C160 Perfs 7661-7873

8191' PBTD (Float Collar)

8225' ; $5 \frac{1}{2}"$, 17 #/ft Csg w/ 800 SX to 5240'

9040 TD

Conoco Inc.

Calculation Sheet

Job No. _____

Made By SAB

Checked By

Date 6/25/86

Title Barbara Federal No. 1

Field _____