

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

JUN 17 1976

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. OG-305
7. Unit Agreement Name -----
8. Farm or Lease Name Millman Deep Corn
9. Well No. 1
10. Field and Pool, or Wildcat Millman Morrow Gas
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER- 2. Name of Operator Hanagan Petroleum Corporation 3. Address of Operator P. O. Box 1737 Roswell, New Mexico 88201 4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1924 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 19S RANGE 28E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3550KB
--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to P & A well as follows (approved by Mr. Gressett by phone): T.D. 11050', PBTD 10994, Mor. Perfs. open 10762-83 & 10876-94-Serf csg. 13 3/8" @ 361' w/cmt. circ.; intermed. csg. 9 5/8" @ 2763' (hope to salvage 500 to 600'); 4 1/2" prod. csg. @ 11050 (hope to salvage approx. 9000')--Intermediate hole size 12 1/2", hole size below 9 5/8" csg. 8 3/4"--Set 20 sx. or bridge plug inside 4 1/2" csg. just above open perfs(10750')-100 foot plug in & out 4 1/2" csg. stub (approx. 9000')-100 foot plugs 7825 to 7925, 5750 to 5850, 3500 to 3600--100 foot plug from 2725-2825 (in & out bot. 9 5/8" csg.)--100 foot plug in & out stub of 9 5/8", 100 sx plug in & out base 13 3/8" @ 361' w/ appropriate marker & sx plug @ surface --Gel mud between all plugs--work to begin when casing puller is available

Pulled Tubing and left Packer in the Hole -
Set & dumped 10 5/8" 14 1/2" 6-28-76 went back in hole and
retrieved pkr then shot pipe @ 9339' 16-29-76 tan
tbg to 9390' - spotted 30 Sx Cem. - spotted 35 Sx Cem @ 6500' -
spotted 35 Sx @ 5850' - 35 Sx @ 3600' - 35 Sx @ 2825' 16-30-76 shot 9 5/8"
@ 743' - tan tbg to 796' & spotted 50 Sx Cem - pulled tbg to 361' & spotted 50 Sx Cem.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Used 10 Sx Cem to plant P&A Mkr
SIGNED Hugh E. Hanagan TITLE Vice President DATE 6/16/76
Witness Nick Tinker

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUN 17 1976

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness

Plugging
TD 11,050 PB TD 10,994
Perf. 10,762-83, 10876-94
13 3/8" 361'
9 5/8" 2763' ~~Intermed~~ Pull 500 or 600'
4 1/2" 11050 Pull 9000'
Plugs 20/sx or bridge plug inside 4 1/2" above perf.
100' Plug at 4 1/2" stub
" " " 7825-7925
" " " 5750-5850
" " " 3500-3600
" " " 2725-2825 in & out 9 5/8"
Stub Plug, in & out 9 5/8" ~~at~~ at start point
in & out 13 3/8" - 300-400