

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
 FEB 7 1973
O. C. C.
ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. K 3256	
7. Unit Agreement Name	
8. Farm or Lease Name STATE A	
9. Well No. I	
10. Field and Pool, or Wildcat SHUGART	
12. County EDDY	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>DRY HOLE</u>
2. Name of Operator JOHN H. TRIGG
3. Address of Operator 1267 MALJAMAR N.MEX. 88264
4. Location of Well UNIT LETTER <u>P</u> , <u>990</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18</u> RANGE <u>31</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3151.6 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 2-8-73 We plan to plug said well as follow.

25 sx plug from 4100-----4000

25 sx plug from 3596-----3496

25 sx plug from 3100 --3000

25 sx plug from 1075 --975

25 sx plug from 550 in 10 in. pipe

10 sx at surface with marker

mud between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Sub. Insp.</u>	DATE <u>2-6-73</u>
APPROVED BY <u>W. Q. Gressett</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>FEB 8 1973</u>
CONDITIONS OF APPROVAL, IF ANY: <u>spot 25sx plug @ base of salt</u>		