Submit 3 Comes to Appropriate District Office

1. Type of Well:

State of New Mexico sergy, Minerals and Natural Resources Departme

Form C-103	1
Form C-103 Revised 1-1-89	V
Walker 1.7 da	

FEE L

DISTRICT P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM \$8210

1000 Rio Brazos Rd., Azlec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OTHER

MET X

PAR 1.9 1993

تا سان

WELL API NO. 5. Indicate Type of Lance STATE X

6. State Oil & Gas Lease No. K-3153

7. Lease Name or Unit Agreement Name

Parkway West Unit

Name of Operator UMC Petroleum Corporat	ion /	8. We	ell No. 1L	i
1. Address of Operator 1201 Louisiana, Suite 1400, Houston, TX 77002 9. Pool same or Wi		ol same or Wildcat Vest Parkway Atoka		
4. Well Location C 660	North Feet From The	1980	Feet Prom The	Line
Section 28	19S Ran		Eddy	County
	10. Elevation (Show whether D 3321 GR	F, RKB, RT, GR, etc.)		
11. Check App NOTICE OF INTE	propriate Box to Indicate N NTION TO:	•	or Other Data JENT REPORT OF:	-
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDO	NMENT X
PULL OR ALTER CASING		CASING TEST AND CEMENT	JOS	
OTHER:		OTHER:	· · · · · · · · · · · · · · · · · · ·	=

work) SEE RULE 1103.

PLUGGED OFF ATOKA ZONE & ATTEMPTED TO RESTORE STRAWN ZONE TO PRODUCTION.

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give partinent dates, including estimated date of starting any proposed

- Set retainer at 10,504' and squeezed 10,484 10,588 with 20 sks Class H cement while holding pressure on Strawn tbg.
- Tagged TOC w/WL at 10,484'. Released Model K, hydraulic set dual pkr. and POOH w/strawn tbg. POOH w/pkr. and Atoka tbg.
- 3. Acidized strawn perfs from 10,246' 10,456 w/pkr at 10,150' to attempt to return Strawn zone to production. Attempt was unsuccessful well is temp. abandon due to excessive water production.

4-50-93

I hereby contry that the refer	wow. Manley	p ad baid. Production Engineer	DATE3-24-93
TYPE OR PRINT HAME	Steve W. Manley	III	713 TELEPHONE NO. 654-9110
• - •	ORIGINAL:SIGNED BY MIKE WILLIAMS SUPERVISOR, DISTRICT IF	117.8	APR 2 2 1993