## State of New Mexico als and Natural Resources Department

Form	C	-10	03
Revis	ed	1-	1-8

District Office			V/
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO P.O. Box 208	^	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	P.O. Box 208 Santa Fe, New Mexico	875942088	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		APR 4'90	6. State Oil & Gas Lease No.
CUNDRY NOT	ICES AND REPORTS ON WEL	LS - c n	
( DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PEI >-101) FOR SUCH PROPOSALS.)	OH PLUG BACK IC A	7. Lease Name or Unit Agreement Name
. Type of Well: OIL GAS WELL WELL	OTHER SWD		OSAGE
Name of Operator	í	•	8. Well No.
YATES PETROLEUM CORPOR	RATION /		9. Pool name or Wildcat
Address of Operator	***** NM 88210	•	North Dagger Draw Upper Penn
105 South 4th St., Art	tesia, NM 80210		
4. Well Location	980 Feet From The North	Line and198	60 Feet From The East Line
Unit Letter G : 1			Edder Courts
Section 21	Township 19S Race 10. Elevation (Show whether	onge 25E	NMPM Eddy County
	10. Elevation (Show whether 3478 GR	Dr, RKD, KI, GK, EIL.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
	: Appropriate Box to Indicate		Report, or Other Data
11. Check	Appropriate Box to indicate		BSEQUENT REPORT OF:
NOTICE OF IN	ITENTION TO:	301	•
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	NG OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND	CEMENT JOB
		1	
		OTHER:	
OTHER:	wines (Clarky state all partison) details.		
12. Describe Proposed or Completed Operators) SEE RULE 1103.		nnd give pertinent dates, inc	luding estimated date of starting any proposed
12. Describe Proposed or Completed Operators SEE RULE 1103.  2-21-90. Set RBP 69 between 1500' and 69 TIH and set cement r (circulate 5 sacks)	190' and tested to 2000 190' to 2000 psi. Move retainer at 1244'. Pres thru hole at 1390' w/25 valve and squeeze 1 bbl Continued in hoel to	psi. Pull pack packer to 1500 sure annulus to	
12. Describe Proposed or Completed Operator SEE RULE 1103.  2-21-90. Set RBP 69 between 1500' and 69 TIH and set cement r (circulate 5 sacks) close 8-5/8" casing Test to 800 psi, OK.	190' and tested to 2000 190' to 2000 psi. Move retainer at 1244'. Pres thru hole at 1390' w/25 valve and squeeze 1 bbl Continued in hoel to jection.	psi. Pull pack packer to 1500 sure annulus to	ker to 1500'. Tested casing ' and dump sand on RBP at 6990'. o 1200 psi. Cement to surface additives. With cement to surface
12. Describe Proposed or Completed Operators SEE RULE 1103.  2-21-90. Set RBP 69 between 1500' and 69 TIH and set cement r (circulate 5 sacks) close 8-5/8" casing Test to 800 psi, OK. Returned well to inj	190' and tested to 2000 190' to 2000 psi. Move retainer at 1244'. Pres thru hole at 1390' w/25 valve and squeeze 1 bbl Continued in hoel to jection.	psi. Pull pack packer to 1500 sure annulus to	ker to 1500'. Tested casing ' and dump sand on RBP at 6990'. o 1200 psi. Cement to surface additives. With cement to surface
12. Describe Proposed or Completed Optwork) SEE RULE 1103.  2-21-90. Set RBP 69 between 1500' and 69 TIH and set cement r (circulate 5 sacks) close 8-5/8" casing Test to 800 psi, OK. Returned well to inj Work completed 2-25-	190' and tested to 2000 190' to 2000 psi. Move retainer at 1244'. Present thru hole at 1390' w/25 valve and squeeze 1 bbl. Continued in hoel to jection.	psi. Pull pack packer to 1500 sure annulus to 0 sx Class C + cement to 140 6990' and wash	ker to 1500'. Tested casing ' and dump sand on RBP at 6990'. o 1200 psi. Cement to surface additives. With cement to surface
12. Describe Proposed or Completed Optwork) SEE RULE 1103.  2-21-90. Set RBP 69 between 1500' and 69 TIH and set cement r (circulate 5 sacks) close 8-5/8" casing Test to 800 psi, OK. Returned well to inj Work completed 2-25-	190' and tested to 2000 190' to 2000 psi. Move retainer at 1244'. Present thru hole at 1390' w/25 valve and squeeze 1 bbl. Continued in hoel to jection.	psi. Pull pack packer to 1500 sure annulus to 0 sx Class C + cement to 140 6990' and wash	ker to 1500'. Tested casing 'and dump sand on RBP at 6990'. o 1200 psi. Cement to surface additives. With cement to surface 0 psi. Drill retainer at 1244'. sand off RBP. POH w/RBP.
12. Describe Proposed or Completed Optwork) SEE RULE 1103.  2-21-90. Set RBP 69 between 1500' and 69 TIH and set cement r (circulate 5 sacks) close 8-5/8" casing Test to 800 psi, OK. Returned well to inj Work completed 2-25-	190' and tested to 2000 190' to 2000 psi. Move retainer at 1244'. Present thru hole at 1390' w/25 valve and squeeze 1 bbl. Continued in hoel to jection.	psi. Pull pack packer to 1500 sure annulus to 0 sx Class C + cement to 140 6990' and wash	ker to 1500'. Tested casing 'and dump sand on RBP at 6990'. o 1200 psi. Cement to surface additives. With cement to surface o psi. Drill retainer at 1244'. sand off RBP. POH w/RBP.
12. Describe Proposed or Completed Operatory) SEE RULE 1103.  2-21-90. Set RBP 69 between 1500' and 69 TIH and set cement r (circulate 5 sacks) close 8-5/8" casing Test to 800 psi, OK. Returned well to inj Work completed 2-25-	190' and tested to 2000 190' to 2000 psi. Move retainer at 1244'. Present thru hole at 1390' w/25 valve and squeeze 1 bbl. Continued in hoel to jection.	psi. Pull pack packer to 1500 sure annulus to 0 sx Class C + cement to 140 6990' and wash	ker to 1500'. Tested casing 'and dump sand on RBP at 6990'. o 1200 psi. Cement to surface additives. With cement to surface o psi. Drill retainer at 1244'. sand off RBP. POH w/RBP.
12. Describe Proposed or Completed Operators SEE RULE 1103.  2-21-90. Set RBP 69 between 1500' and 69 TIH and set cement r (circulate 5 sacks) close 8-5/8" casing Test to 800 psi, OK. Returned well to inj Work completed 2-25-	190' and tested to 2000 190' to 2000 psi. Move retainer at 1244'. Present thru hole at 1390' w/25 valve and squeeze 1 bbl. Continued in hoel to jection.	psi. Pull pack packer to 1500 sure annulus to 0 sx Class C + cement to 140 6990' and wash	ker to 1500'. Tested casing 'and dump sand on RBP at 6990'. o 1200 psi. Cement to surface additives. With cement to surface 0 psi. Drill retainer at 1244'. sand off RBP. POH w/RBP.