

UNITED STATES
DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
Other (Indicate)
on reverse side

Form approved
Bureau of Land Management
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

N.M. 06767

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

DUNDRY NOTICES AND REPORTS ON WELLS

1. INDICATE IF WELL IS TO BE DEEPENED OR PLUG BACK TO A DIFFERENT RESERVOIR
2. APPLICATION FOR PERMIT for such proposals

RECEIVED BY

AUG 3 - 1987

O. C. D.

ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hackberry

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Wildcat Bone Spring

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

25 T19S R30E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

1. NAME OF OPERATOR

Julian Ard

3. ADDRESS OF OPERATOR

303 Main Street Ft. Worth, TX 76102

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' F.N.L. 1980 F.E.L. Sec 25 T19S R30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3306 GR 3327 RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Displace hole with mud.
2. Set C.I. B.P. @ 9200' \pm 35' cement on top.
3. Cut 5 1/2 csg. @ 7180' \pm 150' cement plug @ stub.
must tag this plug. Will set plug with 2 7/8" + bg.
4. Set 150' Cement plug @ 5600' \pm 2 7/8" + bg.
5. Set 100' Cement plug @ 8 5/8" csg. shoe. Tag Plug
6. Set 100' Cement plug @ 3100' \pm S.A.
7. Set 100' Cement plug @ D.V. Tool 2184'
8. Set 100' Cement plug @ 820' \pm 13 3/8" csg. shoe.
9. Set 50' Cement plug @ surface. with Permanent marker Dry Hole.
10. Move equipment off, level off location, close all pits.

RECEIVED
JUL 20 8 11 AM '87
CARTER RESOURCE
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side