

DISTRICT
 INSPECTION
 SECTION
 NAME
 DATE
 MILES
 DISTRICT
 TIME OF DEPARTURE
 TIME OF RETURN
 CAR NO.
 IN THE SPACE BELOW INDICATE THE PURPOSE OF THE TRIP AND THE DUTIES PERFORMED, LISTING WELLS OR LEASES VISITED AND ANY ACTION TAKEN.
 SIGNATURE

Name B.W. Weaver Date 4-10-79 Miles 53 District II
 Time of Departure 8:00 AM Time of Return 4:00 PM Car No. 0F 327
 In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.
 Signature B.W. Weaver

E-15-19-29. Overland Drilg. & Expl. Co. Lowe St. #1. Plug & abandon. Set 35 sx @ 2750 -2650
 35 sx @ 2200-2100
 35 sx @ 1575-1475
 35 sx @ 1075-975
 35 sx @ 340 to

Will tag plug 4-11-79

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H = Housekeeping	U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, 2ndry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D = Drilling
P = Plugging		P = Production
C = Plugging Cleanup		S = Spill
T = Well Test		U = Underground
F = Waterflow		
M = Minor Spill		
W = Well Abandonment		