

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons.
M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210
Bureau No. 1004-0135
Expires March 31, 1993

dsf

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Nearburg Producing Company /

3. Address and Telephone No.
3300 North A Street, Building 2, Suite 120, Midland, Texas 79705 (915) 686-8235

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980' FNL and 1980' FWL, Section 35, T19S, R25E

5. Lease Designation and Serial No.
NM 0504364A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SW948

8. Well Name and No.
Hilliard Gulf Fed Com #1

9. API Well No.
30-015-21066

10. Field and Pool, or Exploratory Area
Cemetary - Morrow

11. County or Parish, State

Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Nearburg Producing Company requests to Plug and Abandon the above referenced well.

- 1) Set CIBP @ 9380; dump 35' cmt on plug
- 2) 6635' perf and squeeze, 100' cement in csg & 100' outside (Top of Wolfcamp 6635')
- 3) Cut 4-1/2" csg @ 4000' & pull
- 4) Set stub plug 50' in & 50' out. WOC. Tag
- 5) Set 35 sx plug (100') f/ 2400' to 2500'. (Top Yeso 2455')
- 6) Set 100' plug f/ 1250' to 1350'. (Base 8-5/8" @ 1300') - T76
- 7) Set 100' plug f/ 250' to 350' (Base 13-3/8" @ 305') - T76
- 8) Set 20" surface plug. 50'
- 9) Install dry hole marker.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL



14. I hereby certify that the foregoing is true and correct

Signed Kim Skuweit
(This space for Federal or State office use)

Title Regulatory Analyst

Date 02/20/2002

Approved by
Conditions of approval, if any:

Title

Date

Accepted for record - NMOCD

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

RECEIVED

2002 FEB 22 AM 8:32

BUREAU OF LAND MGMT.
ROSWELL OFFICE