Submit 3 Copies to Appropriate District Office

DISTRICT II

11

State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St.

V	X)			
WELL API NO. 30 015 21084	V	-		_
Laudia I 😙 💮 🐠				

P.O. Drawer DD, Artesia, NM 88210 DISTRICT III

Santa Fe, NM 87505

sIndicate Type of Lease FEE X STATE

6State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Ivey Com Type of Well: WELL WELL 2Name of Operator «Well No. Nearburg Producing Company 3Address of Operator Pool name or Wildcat 3300 North "A" Street, Building 2, Ste 120, Midland, TX 79705 Wildcat Penn 4Well Location 1980 north 660 Unit Letter Feet From The Line and Feet From The east Line 5 Section **19S** Township Range 26E NMPM Eddy County 10 Elevation (Show whether DF, RKB, RT, GR, etc.) 3368.7' GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER:

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103

Nearburg Producing Company requests to Plug and Abandon the above referenced well.

1. Set CIBP @ 8809' cap w/ 35' cmt. PBTD at 8774'.

2. Set 25 sx plug f/ 6200' to 6000' (Top of Wolfcamp - 6114'). Part CS4 @ 6100 3. Cut 4-1/2" casing @ 5720' & pull.

4. Spot 100' plug 50 in & 50 out of stub. Tag.

Salt gel mud consisting of 10# Brine W/25# of gel per bbl

must be placed between each plug

100' plug 3430-3530 5. Spot 100' plug @ 2575'. (Top of Glorida - 2525')

6. Spot 100' plug f/ 1099' to 1199'. Tag. (8-5/8" shoe @ 1149')

7. Set 60' suface plug. 100' plug

8 Install dry hole marker.

Notify OCD 24 hrs. prior to any work don

hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Regulatory Analyst

01-28-2002 DATE

TYPE OR PRINT NAME Kim Stewart

TELEPHONE NO. 915-686-8235

(This space for State Use)

APPROVED BY

SIGNATURE

CONDITIONS OF APPROVAL, IF ANY:

TITLE Suld Sep P DATE AN 34 2002