

.. 50-015-21262

9-30-74
Acoustic & Delay
Neutron Log.
50-015-21262

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.O.S.	/
LAND OFFICE	/
OPERATOR	/

APR 21 1982
O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name S. P. Johnson
9. Well No. 1
10. Field and Pool, or Wildcat
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☒ OTHER-

2. Name of Operator
Mewborne Oil Company /

3. Address of Operator
P. O. Box 7698 Tyler, Texas 75701

4. Location of Well
UNIT LETTER G 1980 FEET FROM THE FN LINE AND 1980 FEET FROM
THE FE LINE, SECTION 5 TOWNSHIP 20 RANGE 25 NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 4-5-82 Set C.I.B.P. at 9250'. Capped with 35' of cement.
2. 4-6-82 Circulated 4 1/2" casing with 10# PGM.
Cut & pulled 6683' of 4 1/2"
3. 4-8-82 Spotted a 35 sack cement plug down tubing at 6733', 50' in stub.
4. 4-12-82 Tagged plug at ⁶⁵²⁸6228'. P.U.H. with tubing to 6200' and spotted a 35 sack plug.
5. 4-13-82 P.U.H. to 3720', mixed mud and spotted a 35 sack plug. P.U.H. with tubing to 2300' and spotted a 35 sack plug. P.U.H. with tubing to 1300' and spotted a 35 sack plug. P.U.H. and W.O.C. Tagged plug at 1170'. P.U.H. to 350' and spotted a 35 sack plug. P.O.H.
6. 4-14-82 Cut off well head and spotted a 10 sack surface plug. Installed a dry hole marker.

*Posted 10-2
P4A
4-23-82*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Delora Hard TITLE Production Clerk DATE 4-16-82

APPROVED BY Walter Stillfield TITLE OIL AND GAS INSPECTOR DATE JUN 18 1982

CONDITIONS OF APPROVAL, IF ANY: