## Submit 3 Copies to Appropriate District Office

## State of New Mexico L. Minerals and Natural Resources Department

Form	C-103	C.
Revis	ed 1-1-8	9

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION
P.O. Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-21478

5. Indicate Type of Lease
STATE XX FEE

6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 K-6096 SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: WELL X State K OTHER 2. Name of Operator 8. Well No. YATES PETROLEUM CORPORATION RECEIVED 9. Pool name or Wildcat 3. Address of Operator ARTESIA 105 South 4th St., Artesia, NM Dagger Draw Upper Penn, North 4. Well Location \_:\_660 West \_ Feet From The Feet From The \_ \$15020181 Eddy 19S 28 **NMPM** County Township Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3506' KB Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDONMENT **CHANGE PLANS** COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Recomplete to Canyon OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 11-5-97 - Moved in and rigged up pulling unit. 11-6-97 - Pumped 35 bbls 2% KCL. Cut bolts off tree. Nippled down tree. Nippled up BOP. Worked on getting packer unset. Packer dragging up hole. Pulled 6 joints. Packer would not move up or down. Rigged up wireline to cut tubing. TIH with chemical cutter. Found packer at 9109'. Cut tubing at 9095'. Left packer and 14' fishing stub looking up. TOOH with wireline. Rigged down wireline. TOOH with tubing & laid down tubing (290 joints). 11-7-97 - TIH with overshot, bumper sub, jars, drill collars and 2-7/8" tubing. Latched

well in. 11-8-10-97 - Rigged up wireline. TIH with gauge ring and junk basket to 9140'. TOOH. TIH with CIBP and set CIBP at 9140'. TIH with logging tools and ran CBL/CCL/GR log. TOOH with logging tools and rigged down wireline.

11-11-97 - TIH with tubing to 7780'. Pickled tubing with 500 gallons 20% HCL acid.

onto 2-3/8" stub. Jarred packer free. TOOH with tubing, collars, jars and packer.

Spotted 500 gallons 20% double inhibited iron control HCL acid. TOOH with tubing. Rigged

SIONATURE	Operations Technician DATE Nov. 25, 1997
TYPE OR PRINT NAME RUSTY Klein TELEPHONE NO. 505/748-147	