

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO P. O. DRAWER DD - ARTESIA 88210

July 8, 1975

I. R. TRUJILLO CHAIRMAN

LAND COMMISSIONER PHIL R. LUCERO MEMBER

STATE GEOLOGIST A. L. PORTER, JR. SECRETARY – DIRECTOR

Mark Production Company 330 Citizens Bank Building Tyler, Texas 75701

> Re: State D Com #1-N, 16-20-24 Form C-103, cementing report 8 5/8" casing

Gentlemen:

We are in receipt of Subsequent C-103 report on casing and cementing of subject well.

However, the reported cement volume as well as the depths placed does not agree with the actual volumes and depth as was furnished me by your field representative at the well site during the primary and secondary cementing operations.

Please resubmit the above mentioned Form C-103 with the corrected depths and volumes.

The temperature survey indicated 650' as the cement top. Your report does not include this information.

We could not get 1" pipe below 454', you report 800'.

Enclosed is the incorrect C-103s.

Sincerely yours, Leon Bergstrom

LB:jw