

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

RECEIVED

OCT 22 '90

O. C. D.
ARTESIA, OFFICE

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

DRILL STEM TESTS

State "D" #1, V-2531
Unit N, Sec. 16-T20S-R24E
Eddy County, NM

DST #1 5086-5310'. Misrun.

DST #2 5073-5343' (270'): TIMES: 30-60-60-120-60.
RECOVERY: 1200' mud, 1243' sulfur. SAMPLER: 845 psi, 2375 cc water,
.56 cfg. PRESSURES: IHP 2676, FHP 2676, IFP 352-455, ISIP 1982, 2nd
FP 605-872, FSIP 1982, FFP 1038-1201.