

NO. OF COPIES RECEIVED	13
DISTRIBUTION	
ANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-4-65

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 17 1976

3 - NMOCC - Artesia
1 - File
2 - Mesa Petr.
1 - Monsanto

O.C.C.
1-Kang Resources

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Getty Oil Company ✓	8. Farm or Lease Name State K 6096 "B"
3. Address of Operator P. O. Box 249, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER G, 1650 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 19S RANGE 25E NMPM.	10. Field and Pool, or Wildcat Undesig. Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3475' Gr.	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

It is proposed to plug and abandon as follows: An attempt to pull casing from 5800'. Will mud up, leaving mud between all plugs.

- A. 100' plug in and out of stub. (5½")
- B. 100' plug 3550-3650 (Across Abo Top)
- C. 100' plug 2150-2250 (Across Glorieta Top)
- D. 100' plug 1250-1350 (In and out of Intermediate casing shoe)
- E. 10 sack cement at surface with dry hole marker

Clean up location.

Verbal approval has been received for above procedure.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>C. E. Hado</u>	TITLE <u>Area Supt.</u>	DATE <u>3-16-76</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>MAR 17 1976</u>
CONDITIONS OF APPROVAL, IF ANY:		