

MOCC COPY  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIP  
(Other instructions  
reverse side)

copy to SP  
Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. WELL OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Westall - Mask		8. FARM OR LEASE NAME Hinkle "B" Federal	
3. ADDRESS OF OPERATOR P.O. Drawer 1477 Roswell, N.M. 88201		9. WELL NO. #6	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FNL and 1,650' FWL		10. FIELD AND POOL, OR WILDCAT Shugart	
14. PERMIT NO.		13. STATE N.Mex.	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3,626 GR.		12. COUNTY OR PARISH Eddy	

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(Other) Plugback + perforate X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is plugged back, give surface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to set a plug @ 2,775' and perforate the holes between 2,500' to 2,750'.

We failed to submit this form prior to doing the work because of an oversight.

RECEIVED  
JAN 20 1978  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

19. I hereby certify that the foregoing is true and correct

SIGNED Jack Mask TITLE Co-Owner DATE 01/19/78

(This space for Federal or State office use)

APPROVED BY Lee H. Lusa TITLE ACTING DISTRICT ENGINEER DATE JAN 24 1978

CONDITIONS OF APPROVAL, IF ANY: