
Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department



DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION WELL ARE

	Form C-103 Revised 1-1-89	$\rho^+$
I NO.		

P.O. Box 2088	WELL AFI NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexic 388	\$\text{\$\exitt{\$\text{\$\text{\$\text{\$\text{\$\exitt{\$\text{\$\exitt{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\exititt{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\}}\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\tex{	
DISTRICT III ALIC	2 6 1993 STATE X FEE	
	6. State Oil & Gas Lease No. 648	
SUNDRY NOTICES AND REPORTS ON WELL		
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN (	OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE *APPLICATION FOR PER	MIT 7. Lease Name or Unit Agreement Name	
(FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:	= m'll	
	E. Mill man	
	DHY State A	
2. Name of Operator	8. Well No.	
SDX Resources, Inc. 5 3. Address of Operator	± #219	
•	9. Pool name or Wildcat	
P. O. Box 5061, Midland, Texas 79704	E. Millman-Q-GR-SA	
Unit Letter <u>J</u> : 1650 Feet From The East	Line and 1980 Feet From The South Line	
	nge 28E NMPM Eddy County	
10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	
(/////////////////////////////////////		
11. Check Appropriate Box to Indicate 1	Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
	- CODDEGOENT HEI ONI OI:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB	
OTHER.		
OTHER:	OTHER: Re-enter X	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, as work) SEE RULE 1103.	1.  If you persinent dates, including estimated date of starting any proposed	
August 13, 1993		
1 757		
1. Dig work over pit.		
<ul><li>2. Dig out around 8 5/8" casing.</li><li>3. Cut off and remove dry hole marke</li></ul>	r	
4. Weld on 8 5/8" casing stub to sur		
T. Werd off o 5/0 caping boar to sar	# # C C F	

TYPEORPRINTNAME Rebecca Robinson			<u>телетноме но 748 – 972</u>
SIGNATURE ROUCE ROVINSON TITLE	Agent for	SDX	B-26-93
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			

MIKE WILLIAMS

SUPERVISOR, DISTRICT IT

SEP - 7 1993