

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY  
P. O. BOX 2038  
SANTA FE, NEW MEXICO 87501  
OCT 4 - 1985  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1

5a. Indicate Type of Lease  
State ☐ For ☒  
5. State Oil & Gas Lease No.  
-----

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Penroc Oil Corporation ✓ 3. Address of Operator P O DRAWER 831, MIDLAND TX 79702 4. Location of Well UNIT LETTER B 1980 FEET FROM THE East LINE AND 660 FEET FROM THE North LINE, SECTION 33 TOWNSHIP 19S RANGE 28E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3340 GR	7. Unit Agreement Name ----- 8. Farm or Lease Name Angell Ranch Comm. 9. Well No. 1 10. Field and Pool, or Wildcat Winchester Morrow 12. County Eddy
---	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-12-85 Set CIBP @ 10,800'. Bailer dump 35' cement plug on top CIBP. Pressure 4½" csg. to 1500# for 30 min. holds OK. CIBP above Morrow perfs 10912-10956'. Perforate Wolfcam Lime thru 4½" csg. w/l jet shot/ft. 8956-8964', 8912-8918', 8897-8908'.  
9-18-85 After repair unit, swab to test. Have only slight show gas.  
9-19-85 Acidize perfs 8908-8956' w/500 gals. 15% NE acid. Total load 48 bbls. Swab to test. No flow of gas.  
9-20-85 Perforate 9350-9354' (This not included on C-103 Notice of Intent) Swab to test. Rec gas cut load water.  
9-21-85 Continue to swab and test recsli gas cut load water.  
9-23-85 Trip in and out of hole to replace packer. Swab to test. Rec Gas cut load water.  
9-24-85 On swab test rec sli gas cut salt water. Release unit. Close well in.

Note: Well is temporarily abandoned pending decision of interest owners for future plans.

Post FD-2  
10-11-85  
PWA mnr.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. J. Dally TITLE President DATE 10-3-85  
Original Signed By  
Mike Williams  
Oil & Gas Inspector  
APPROVED BY \_\_\_\_\_ DATE OCT 8 1985  
CONDITIONS OF APPROVAL, IF ANY: