

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION *clst*
Drawer DD
Artesia, NM ~~NOT APPROVED~~

Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM-18959

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Dagger Draw 1

9. API Well No.

30-01521966

10. Field and Pool, or Exploratory Area

Dagger Draw Strawn Gas

11. County or Parish, State

Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P, Inc.

3. Address and Telephone No.

PO Box 3109; Midland, Texas 79701 (915) 688-4816

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit ~~Letter O~~ 660' FSL 1980' FEL
Sec 32 T-19S Range 25E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) Notify BLM of intent to Plug and Abandon well. Mix 25# per bbl salt gel mud w/ 9.5# brine, & CIRC well bore.
- 2) Pull stretch on csg & cut csg & pull same @ 6500'. Top of cmt by temp survey @ 7040'.
- 3) Spot 60 sx cmt plug f/ 6550 -6450' - stub plug 50' inside csg, 8 3/4" hole.
- 4) Spot 60 sx cmt plug f/ 6134'-6034' (wolfcamp top 6084')
- 5) Spot 60 sx cmt plug f/ 3983'-3883' (bonesprings 3933')
- 6) Spot 60 sx cmt plug f/ 2292 -2192 (Glorietla top 2242')
- 7) Spot 60 sx cmt plug f/ 1424 -1324' (9 5/8" shoe plug)
- 8) Spot 55 sx cmt plug f/ 445' - 345'. (13 3/8" shoe plug)
- 9) Spot 55 sx cmt plug f/ 100' - surface
- 10) Nipple down BOP & cut off wellhead; cap well; install dry hole marker, clean location
- 11) Rig down & move off.

RECEIVED

JUL 07 1995

OIL CON. DIV.

Dist. 2

14. I hereby certify that the foregoing is true and correct

Signed *[Signature]*

Title Operating Engineer

Date July 7, 1995

(This space for Federal or State official use)

(ORIG. SGD.) JOE G. LARA

PETROLEUM ENGINEER

Date 8/1/95

Approved by
Conditions of approval, if any:

See attached.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side