

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-015-22023

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
K-6653

7. Lease Name or Unit Agreement Name  
Millman HD State Com

8. Well No.  
1

9. Pool name or Wildcat  
Undes. Canyon

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT, OFFICE  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER RECOMPLETION

2. Name of Operator  
YATES PETROLEUM CORPORATION

3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location  
Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line  
Section 17 Township 19S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3530' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Plugback, perforate, treat <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-5-90. Set CIBP at 10800' w/30' cement on top. Perforated 9730-9965' w/24 - .42" holes as follows: 9730, 33, 36, 42, 48, 50, 60, 62, 64, 66, 69, 75, 85 and 9788 (14 holes); 9956, 57, 58, 59, 60, 61, 62, 63, 64 and 9965 (10 holes). Acidized in two stages w/2500 gals 15% NEFE acid and ball sealers. Swabbed well with show of gas during run and skim of oil.

4-11-90. Perforated 9371-9408' w/34 - .42" holes as follows: 9371, 72, 73, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 9406, 07 and 9408', (2 SPF). Acidized perforations 9371-9408' w/2500 gals 20% NEFE acid and 50 ball sealers. Swabbed, recovered 58 bbls with show of acid gas with skim of oil.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-12-90  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT II TITLE  DATE APR 17 1990

CONDITIONS OF APPROVAL, IF ANY: