

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Geology, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Ruo Brazos Rd., Aztec, NM 87410

MAY 17 '90

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-0158
7. Lease Name or Unit Agreement Name  Chaparral State
8. Well No. #1
9. Pool name or Wildcat Winchester Bone Spring
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3280' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Strata Production Company

3. Address of Operator  
648 Petroleum Bldg., Roswell, NM 88201

4. Well Location  
Unit Letter E : 1880 Feet From The North Line and 660 Feet From The West Line  
Section 32 Township 19s Range 29e NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- A) Perforate First Bonespring sandstone @ 6758 - 6780' W/12 holes.
- B) Acidize w/1200 gals 15% NEFE.
- C) If necessary, Frac w/40,000#20/40 & 8000# 16/30 sand w/CO<sub>2</sub> & 20,000 gals of crosslinked gel.
- D) Remove RBP @ 6800' & commence pumping.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James G. McClelland TITLE Vice President DATE 5-15-90

TYPE OR PRINT NAME James G. McClelland TELEPHONE NO. \_\_\_\_\_

(This space for State Use) ORIGINAL SIGNED BY  
**MIKE WILLIAMS**  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE **MAY 21 1990**

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_