

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Shut In		5. LEASE DESIGNATION AND SERIAL NO. NM-0556285	
2. NAME OF OPERATOR Southern Union Exploration Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 1201 Elm Street, Suite 1900, Dallas, Texas 75270		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FEL and 1980' FSL		8. FARM OR LEASE NAME Exxon Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3761' GL		10. FIELD AND POOL, OR WILDCAT W. Bubbling Springs	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 26, T20S, R25E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

1. Notify BLM at (505) 887-6544 prior to operation.
2. RU on well and displace hole with 9 ppg mud. POH.
3. RIH and set CIBP at approximately 9500'. Place 50' cement on CIBP.
4. Run free point on 4 1/2" casing.
5. Cut and retrieve free 4 1/2" casing (Estimate - 6000').
6. Spot 100' cement plug across 4 1/2" casing stub. (50' in, 50' out) Tag plug.
7. Spot 100' cement plug from 2550'-2450'. Tag plug. SPOT CMT. PLUG FROM 420'-320'. TAG PLUG.
8. Spot 50' cement plug from 50'-0'.
9. Install dryhole marker as per BLM specifications.
10. Restore location.

Note: Will use Class "C" cement with 2% CaCl<sub>2</sub>.

RECEIVED  
NOV 15 12 16 PM '90  
CARRIZO  
AREA  
LENS

18. I hereby certify that the foregoing is true and correct

SIGNED <u>D. P. - Operations</u>	TITLE <u>V. P. - Operations</u>	DATE <u>11/12/90</u>
(This space for Federal or State office use)		
APPROVED BY <u></u>	TITLE <u></u>	DATE <u>12-4-90</u>
CONDITIONS OF APPROVAL, IF ANY:		

\*See Instructions on Reverse Side