

FIELD Turkey Track Morrow COUNTY Eddy OCC NUMBER _____

OPERATOR Hondo Drilling Company ADDRESS Drawer 2516, Midland, Texas 79702

LEASE Exxon-State Com. WELL NO. 1 SURVEY 660' FNL & 1980' FWL, Section 17, T-19S, R-29E

RECORD OF INCLINATION

<u>DEPTH (FEET)</u>	<u>ANGLE OF INCLINATION (DEGREES)</u>
365'	1/2
858'	1/4
1,240'	1
1,465'	1-1/4
1,667'	1-1/4
2,155'	1-1/2
2,652'	1
3,252'	3/4
3,745'	1
4,240'	1
4,716'	2
4,875'	2-1/4
5,058'	2-1/4
5,248'	2-3/4
5,500'	4-1/2
5,605'	6
5,667'	6
5,724'	6
5,814'	6
5,910'	5-1/2
5,960'	5-1/2
6,073'	4-1/2
6,230'	3-3/4
6,573'	2-3/4
7,034'	2-3/4
7,227'	3
7,290'	3
7,510'	2-3/4
8,008'	1-1/2
8,385'	1
8,850'	3/4
9,190'	1-3/4
9,850'	5-1/4
9,961'	5
10,147'	4-1/4
10,455'	3
10,559'	1-1/2
11,390'	1-1/2

RECEIVED

APR 1 1977

O. C. C.
LUTHERIA, OFFICE

Certification of personal knowledge Inclination Data:

I hereby certify that I have personally assembled the data and facts placed on this form, and such information given above is true and complete to the best of my knowledge.

HONDO DRILLING COMPANY

BY: 
Walter Frederickson
Vice President

1. The first step in the process of the investigation is the identification of the problem. This is done by the investigator who is responsible for the investigation. The investigator must identify the problem and the scope of the investigation. The investigator must also identify the objectives of the investigation and the methods to be used.

SECRET


772 1947

[illegible]

19340 10/11/1961 1000000 1000000 1000000

— *Journal of the American Medical Association*, 1997

Sworn and subscribed to before me the undersigned authority, on this the
31st day of March, 1977.

 Notary Public in and for Midland County, Texas.
Joyce Wood