

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 1530

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal HF

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

North McMillan Grayburg

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Unit A, Sec. 10-T19S-R27E

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

105 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

660' FNL & 660' FEL, NE/NE, Sec. 10-19S-27E

14. PERMIT NO.

API #30-015-22059

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3475' GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other) Continue Suspended Production X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Due to economic conditions this well has been suspended from production. The suspension expires May 31, 1989. Yates Petroleum Corporation would like to continue the well in suspension and ask for your approval.

1. Lease is in its extended term.
2. All wells on this lease are plugged and abandoned.
3. The well is capable of producing as a stripper well, however failure to suspend the production could lead to premature abandonment. Prior to suspension, the well could only produce 1 day a week before it had to be shut-in for buildup.
4. The last production from this well was February 2, 1987, with production of 3 BOPD.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE Production Supervisor

DATE 5-8-89

(This space for Federal or State office use)

APPROVED BY *[Signature]*
CONDITIONS OF APPROVAL, IF ANY:

FOR: *[Signature]*
TITLE

DATE 5-19-89

*See Instructions on Reverse Side