

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. N/A
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647
7. Lease Name or Unit Agreement Name East Millman Unit
8. Well No. 202
9. Pool name or Wildcat E. Millman-Q-G-SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	FEB - 3 1994
2. Name of Operator SDX RESOURCES, INC.	
3. Address of Operator P. O. BOX 5061, MIDLAND, TX 79704	
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>22</u> Township <u>19-S</u> Range <u>28-E</u> NMPM <u>EDDY</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3382 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	Re-entry <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/02/93 Remove dry hole marker and weld on 9 5/8" csg stub.

9/03-9/08-93 Drill cement plugs and cement retainer with 8 5/8" bit, surface to 2601'. Test csg.

9/09/93 Perforate 25 holes: 2078, 79, 83, 96, 98, 2138, 40, 93, 97, 2220, 21, 37, 45, 48, 57, 62, 75, 81, 91, 2314, 58, 63, 2438, 44, 48. Acidize well with 3,000 gal of NEFE 15% acid. Frac with 40,000 gal X/L gel with 1,000 sx 12/20 Brady sand.

9/12/93 Run tubing, rods and pump. Begin pumping back load.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Barbara E. Wickham TITLE Prod. Analyst DATE 01-17-94
TYPE OR PRINT NAME Barbara E. Wickham TELEPHONE NO. 685-1761

(This space for State Use)

APPROVED BY SUPERVISOR, DISTRICT II TITLE _____ DATE FEB 3 1994
CONDITIONS OF APPROVAL, IF ANY